

## CABLE AND CONDUIT A

Buyer: SPRMM1 DLA MECHANICSBURG

---

### Description:

ITEM UNIQUE IDENTIFICATION AND VALUATION (MAR 2016)|19|||||||||||||  
HIGHER-LEVEL CONTRACT QUALITY REQUIREMENT (NAVICP REVIEW FEB 1991)(FEB 1999)|1|ISO9001 or any other higher level contract quality requirements included in the TDP|  
INSPECTION OF SUPPLIES--FIXED-PRICE (AUG 1996)|2||  
EQUAL OPPORTUNITY (SEP 2016)|2||  
BUY AMERICAN --FREE TRADE AGREEMENTS--BALANCE OF PAYMENTS PROGRAM - BASIC(DEVIATION 2020-O0019) (JUL 2020))|3|||  
ALTERNATE A, ANNUAL REPRESENTATIONS AND CERTIFICATIONS (NOV 2020)|13|||||||||  
BUY AMERICAN-FREE TRADE AGREEMENTS-BALANCE OF PAYMENTS PROGRAM CERTIFICATE (DEVIATION 2020-O0019) (JUL 2020))|3|||  
BUY AMERICAN-BALANCE OF PAYMENTS PROGRAM CERTIFICATE-BASIC (NOV 2014)|1||  
ANNUAL REPRESENTATIONS AND CERTIFICATIONS (JAN 2022)|13|336413|1250|||||||  
NOTICE OF PRIORITY RATING FOR NATIONAL DEFENSE, EMERGENCY PERPARDENESS, AND ENRGY PROGAM USE (APRIL 2008))|2||x|  
EVALUATION CRITERIA AND BASIS FOR AWARD-|1||

This is an FMS requirement; therefore, surplus is not acceptable.

RFID is only required if the ship to code identified above is listed at the website within DFARS 252.211-7006 PASSIVE RFID, at the time of shipment. Currently there are no locations listed that require passive RFID tagging.

Inspection of material will be at:

---

Inspection of packaging and final acceptance of material will be at:

---

Any order resulting from this Request for Quotation will require electronic submittal of Receiving Reports and Invoices through PIEE-WAWF.

Quoted delivery is \_\_\_\_ days ADC.

All contractual documents (i.e. Contracts, Purchase Orders, Task Orders, Delivery Orders and Modifications) related to the instant procurement are considered to be "Issued" by the Government when copies are either deposited in the mail, transmitted by Facsimile, or sent by other electronic commerce methods such as email. The Government's acceptance of the contractor's proposal constitutes bilateral agreement to "Issue" contractual documents as detailed herein.

### NOTICE TO SURPLUS SUPPLIERS:

SUBMISSION OF YOUR QUOTE WITHOUT A SURPLUS CERTIFICATE WILL NULL AND VOID YOUR QUOTE. A SURPLUS MATERIAL CERTIFICATE MUST ACCOMPANY ALL QUOTES FOR SURPLUS MATERIAL. IF SUBMITTING QUOTE VIA EDI, PLEASE EMAIL A COPY OF THE COMPLETED SURPLUS CERTIFICATE TO THE BUYER POC LISTED ON THE SOLICITATION.

#### 1. SCOPE

1.1 This contract/purchase order contains the requirements for manufacture and the contract quality requirements for the CABLE AND CONDUIT A .

#### 2. APPLICABLE DOCUMENTS

2.1 Applicable Documents - The document(s) listed below form a part of this contract/purchase order including modifications or exclusions.

2.1.1 Documents, drawings, and publications supplied are listed under "Drawing Number". These items should be retained until an award is made.

2.1.2 "Document References" listed below must be obtained by the Contractor. Ordering information is included as an attachment to this contract/purchase order.

2.2 Order of Precedence - In the event of a conflict between the text of this contract/purchase order and the references and/or drawings cited herein, the text of this contract/purchase order shall take precedence. Nothing in this contract/purchase order,

however, shall supersede applicable laws and regulations unless a specific exemption has been obtained.

2.3 ;Requests for additional government-owned documents should be submitted in writing to the contract officer responsible for the applicable order. Release of drawings or other documents will be approved and handled by the technical community for the

system.;

DRAWING DATA=WS19179 |53711| E| |D|0001 | E|49998|0034407  
DRAWING DATA=WS19179 |53711| E| |D|0001.A | B|49998|0019525  
DRAWING DATA=WS19179 |53711| E| |D|0002 | E|49998|0034440  
DRAWING DATA=WS19179 |53711| E| |D|0003 | E|49998|0026528  
DRAWING DATA=WS19179 |53711| E| |D|0004 | E|49998|0028216  
DRAWING DATA=WS19179 |53711| E| |D|0005 | E|49998|0048490  
DRAWING DATA=WS19179 |53711| E| |D|0006 | E|49998|0049626  
DRAWING DATA=WS19179 |53711| E| |D|0007 | E|49998|0027931  
DRAWING DATA=WS19179 |53711| E| |D|0008 | E|49998|0043460  
DRAWING DATA=WS19179 |53711| E| |D|0009 | E|49998|0030041  
DRAWING DATA=WS19179 |53711| E| |D|0010 | E|49998|0036722  
DRAWING DATA=WS19179 |53711| E| |D|0011 | E|49998|0037320  
DRAWING DATA=WS19179 |53711| E| |D|0012 | E|49998|0024707  
DRAWING DATA=WS19179 |53711| E| |D|0013 | E|49998|0015178  
DRAWING DATA=WS19179 |53711| E| |D|0014 | E|49998|0028376  
DRAWING DATA=WS19179 |53711| E| |D|0015 | E|49998|0026390  
DRAWING DATA=WS19179 |53711| E| |D|0016 | E|49998|0017952  
DRAWING DATA=WS19179 |53711| E| |D|0017 | E|49998|0026422  
DRAWING DATA=WS19179 |53711| E| |D|0018 | E|49998|0026310  
DRAWING DATA=WS19179 |53711| E| |D|0019 | E|49998|0016079  
DRAWING DATA=WS19179 |53711| E| |D|0020 | E|49998|0015728  
DRAWING DATA=WS19179 |53711| E| |D|0021 | E|49998|0017880  
DRAWING DATA=WS19179 |53711| E| |D|0022 | E|49998|0038330  
DRAWING DATA=WS19179 |53711| E| |D|0022.A | D|49998|0012235  
DRAWING DATA=WS19179 |53711| E| |D|0023 | E|49998|0021392  
DRAWING DATA=WS19179 |53711| E| |D|0024 | E|49998|0023792  
DRAWING DATA=WS19179 |53711| E| |D|0025 | E|49998|0017278  
DRAWING DATA=WS19179 |53711| E| |D|0026 | E|49998|0035092  
DRAWING DATA=WS19179 |53711| E| |D|0027 | E|49998|0041731  
DRAWING DATA=WS19179 |53711| E| |D|0028 | E|49998|0040508  
DRAWING DATA=WS19179 |53711| E| |D|0029 | E|49998|0032601  
DRAWING DATA=WS19179 |53711| E| |D|0030 | E|49998|0047045  
DRAWING DATA=WS19179 |53711| E| |D|0031 | E|49998|0044768  
DRAWING DATA=WS19179 |53711| E| |D|0032 | E|49998|0017729  
DRAWING DATA=WS19179 |53711| E| |D|0033 | E|49998|0017804  
DRAWING DATA=WS19179 |53711| E| |D|0034 | E|49998|0042357  
DRAWING DATA=WS19179 |53711| E| |D|0035 | E|49998|0041415

DRAWING DATA=WS19179 |53711| E| |D|0036 | E|49998|0043029  
DRAWING DATA=WS19179 |53711| E| |D|0037 | E|49998|0035294  
DRAWING DATA=WS19179 |53711| E| |D|0038 | E|49998|0036277  
DRAWING DATA=WS19179 |53711| E| |D|0039 | E|49998|0044466  
DRAWING DATA=WS19179 |53711| E| |D|0040 | E|49998|0045003  
DRAWING DATA=WS19179 |53711| E| |D|0041 | E|49998|0042869  
DRAWING DATA=WS19179 |53711| E| |D|0042 | E|49998|0028357  
DRAWING DATA=WS19179 |53711| E| |D|0043 | E|49998|0025686  
DRAWING DATA=WS19179 |53711| E| |D|0044 | E|49998|0044684  
DRAWING DATA=WS19179 |53711| E| |D|0045 | E|49998|0022406  
DRAWING DATA=WS19179 |53711| E| |D|0046 | E|49998|0014697  
DRAWING DATA=WS19179 |53711| E| |D|0047 | E|49998|0026351  
DRAWING DATA=WS19179 |53711| E| |D|0048 | E|49998|0034753  
DRAWING DATA=WS19179 |53711| E| |D|0049 | E|49998|0020625  
DRAWING DATA=WS19179 |53711| E| |D|0050 | E|49998|0020446  
DRAWING DATA=WS19179 |53711| E| |D|0051 | E|49998|0048145  
DRAWING DATA=WS19179 |53711| E| |D|0052 | E|49998|0033821  
DRAWING DATA=WS19179 |53711| E| |D|0053 | E|49998|0035373  
DRAWING DATA=WS19179 |53711| E| |D|0054 | E|49998|0033669  
DRAWING DATA=WS19179 |53711| E| |D|0055 | E|49998|0040759  
DRAWING DATA=WS19179 |53711| E| |D|0056 | E|49998|0017341  
DRAWING DATA=WS19179 |53711| E| |D|0056.A | D|49998|0034642  
DRAWING DATA=WS19179 |53711| E| |D|0056.B | D|49998|0021179  
DRAWING DATA=WS19179 |53711| E| |D|0057 | B|49998|0039979  
DRAWING DATA=WS19179 |53711| E| |D|0058 | D|49998|0034665  
DRAWING DATA=WS19179 |53711| E| |D|0059 | B|49998|0028297  
DRAWING DATA=WS19179 |53711| E| |D|0060 | B|49998|0020809  
DRAWING DATA=WS19199/2 |53711| -| |D|0001 | -|49998|0027515  
DRAWING DATA=WS19199/2 |53711| -| |D|0002 | -|49998|0026166  
DRAWING DATA=WS19199/2 |53711| -| |D|0003 | -|49998|0025938  
DRAWING DATA=WS19199/2 |53711| -| |D|0004 | -|49998|0011931  
DRAWING DATA=WS19199/2 |53711| 4|1N |D|0001 | 4|49998|8353103  
DRAWING DATA=WS19199/2 |53711| 4|1N |D|0002 | 4|49998|0022952  
DRAWING DATA=WS19199/2 |53711| 4|1N |D|0003 | 4|49998|0023382  
DRAWING DATA=WS19202 |53711| -| |D|0001 | -|49998|0024346  
DRAWING DATA=WS19202 |53711| -| |D|0002 | -|49998|0021258  
DRAWING DATA=WS19202 |53711| -| |D|0003 | -|49998|0027412  
DRAWING DATA=WS19202 |53711| -| |D|0004 | -|49998|0008682  
DRAWING DATA=WS19202 |53711| 3|1N |D|0001 | 2|49998|0026254  
DRAWING DATA=WS19202 |53711| 3|1N |D|0002 | 2|49998|0027038  
DRAWING DATA=WS19202 |53711| 3|1N |D|0003 | 2|49998|0035029  
DRAWING DATA=WS20115 |53711| A| |D|0001 | A|49998|0030989  
DRAWING DATA=WS20115 |53711| A| |D|0002 | A|49998|0033033  
DRAWING DATA=WS20115 |53711| A| |D|0003 | A|49998|0030706  
DRAWING DATA=WS20115 |53711| A| |D|0004 | A|49998|0034172  
DRAWING DATA=WS20115 |53711| A| |D|0005 | A|49998|0039393  
DRAWING DATA=WS20115 |53711| A| |D|0006 | A|49998|0036614  
DRAWING DATA=WS20115 |53711| A| |D|0007 | A|49998|0043415  
DRAWING DATA=WS20115 |53711| A| |D|0008 | A|49998|0050708

DRAWING DATA=WS20115 |53711| A| |D|0009 | A|49998|0039126  
DRAWING DATA=WS20115 |53711| A| |D|0010 | A|49998|0039784  
DRAWING DATA=WS20115 |53711| A| |D|0011 | A|49998|0033572  
DRAWING DATA=WS20115 |53711| A| |D|0012 | A|49998|0048482  
DRAWING DATA=WS20115 |53711| A| |D|0013 | A|49998|0044853  
DRAWING DATA=WS20115 |53711| A| |D|0014 | A|49998|0041288  
DRAWING DATA=WS20115 |53711| A| |D|0015 | A|49998|0044742  
DRAWING DATA=WS20115 |53711| A| |D|0016 | A|49998|0042305  
DRAWING DATA=WS20115 |53711| A| |D|0017 | A|49998|0053002  
DRAWING DATA=WS20115 |53711| A| |D|0018 | A|49998|0056829  
DRAWING DATA=WS20115 |53711| A| |D|0019 | A|49998|0048137  
DRAWING DATA=WS20115 |53711| A| |D|0020 | A|49998|0045643  
DRAWING DATA=WS20115 |53711| A| |D|0021 | A|49998|0046669  
DRAWING DATA=WS20115 |53711| A| |D|0022 | A|49998|0037655  
DRAWING DATA=WS20115 |53711| A| |D|0023 | A|49998|0039463  
DRAWING DATA=WS20115 |53711| A| |D|0024 | A|49998|0045506  
DRAWING DATA=WS20115 |53711| A| |D|0025 | A|49998|0050647  
DRAWING DATA=WS20115 |53711| A| |D|0026 | A|49998|0047170  
DRAWING DATA=WS20115 |53711| A| |D|0027 | A|49998|0039749  
DRAWING DATA=WS20115 |53711| A| |D|0028 | A|49998|0033460  
DRAWING DATA=WS20115 |53711| A| |D|0029 | A|49998|0037834  
DRAWING DATA=WS20115 |53711| A| |D|0030 | A|49998|0030560  
DRAWING DATA=WS20115 |53711| A| |D|0031 | A|49998|0035276  
DRAWING DATA=WS20115 |53711| A| |D|0032 | A|49998|0044363  
DRAWING DATA=WS20115 |53711| A| |D|0033 | A|49998|0033185  
DRAWING DATA=WS20115 |53711| A| |D|0034 | A|49998|0039688  
DRAWING DATA=WS20115 |53711| A| |D|0035 | A|49998|0042248  
DRAWING DATA=WS20115 |53711| A| |D|0036 | A|49998|0046869  
DRAWING DATA=WS20115 |53711| A| |D|0037 | A|49998|0051051  
DRAWING DATA=WS20115 |53711| A| |D|0038 | A|49998|0040994  
DRAWING DATA=WS20115 |53711| A| |D|0039 | A|49998|0023827  
DRAWING DATA=WS20115 |53711| A| |D|0040 | A|49998|0030870  
DRAWING DATA=WS20115 |53711| A| |D|0041 | A|49998|0012594  
DRAWING DATA=WS20115 |53711| A| |D|0042 | A|49998|0026142  
DRAWING DATA=WS20115 |53711| A| |D|0043 | A|49998|0020323  
DRAWING DATA=WS20115 |53711| A| |D|0044 | A|49998|0031307  
DRAWING DATA=WS20115 |53711| A| |D|0045 | A|49998|0021677  
DRAWING DATA=WS20115 |53711| A| |D|0046 | A|49998|0021235  
DRAWING DATA=WS20115 |53711| A| |D|0047 | A|49998|0023033  
DRAWING DATA=WS20115 |53711| A| |D|0048 | A|49998|0025226  
DRAWING DATA=WS20115 |53711| A| |D|0049 | A|49998|0022044  
DRAWING DATA=WS20115 |53711| A| |D|0050 | A|49998|0023015  
DRAWING DATA=WS20115 |53711| A| |D|0051 | A|49998|0015497  
DRAWING DATA=WS20115 |53711| A| |D|0052 | A|49998|0026087  
DRAWING DATA=WS20115 |53711| A| |D|0053 | A|49998|0023636  
DRAWING DATA=WS20115 |53711| A| |D|0054 | A|49998|0012518  
DRAWING DATA=WS20115 |53711| A| |D|0055 | A|49998|0087005  
DRAWING DATA=253622 |90536| K| |D|0001 | K|49998|0183511  
DRAWING DATA=253623 |90536| N| |D|0001 | N|49998|0194479

DRAWING DATA=253658 |90536| M| |D|0001 | M|49998|0046500  
DRAWING DATA=253658 |90536| M| |D|0002 | -|49998|0022333  
DRAWING DATA=253659 |90536| J| |D|0001 | J|49998|0028882  
DRAWING DATA=259056 |90536| Y| |D|0001 | Y|49998|0110844  
DRAWING DATA=259056 |90536| Y| |D|0002 | R|49998|0026983  
DRAWING DATA=259056 |90536| Y| |D|0003 | R|49998|0029198  
DRAWING DATA=259056 |90536| Y| |D|0004 | R|49998|0028379  
DRAWING DATA=259056 |90536| Y| |D|0005 | R|49998|0029769  
DRAWING DATA=259056 |90536| Y| |D|0006 | R|49998|0025723  
DRAWING DATA=259056 |90536|AG|PL |D|0001 |AG|49998|0029595  
DRAWING DATA=259056 |90536|AG|PL |D|0002 |AG|49998|0028574  
DRAWING DATA=259056 |90536|AG|PL |D|0003 |AG|49998|0032302  
DRAWING DATA=259056 |90536|AG|PL |D|0004 |AG|49998|0030354  
DRAWING DATA=259056 |90536|AG|PL |D|0005 |AG|49998|0018557  
DRAWING DATA=259056 |90536|AG|PL |D|0006 |AD|49998|0076180  
DRAWING DATA=259056 |90536|AG|PL |D|0007 |AD|49998|0078114  
DRAWING DATA=259056 |90536|AG|PL |D|0008 |AD|49998|0075546  
DRAWING DATA=259056 |90536|AG|PL |D|0009 |AD|49998|0078221  
DRAWING DATA=259056 |90536|AG|PL |D|0010 |AD|49998|0076547  
DRAWING DATA=259056 |90536|AG|PL |D|0011 |AD|49998|0075584  
DRAWING DATA=259056 |90536|AG|PL |D|0012 |AD|49998|0077113  
DRAWING DATA=259056 |90536|AG|PL |D|0013 |AD|49998|0074828  
DRAWING DATA=259056 |90536|AG|PL |D|0014 |AD|49998|0072045  
DRAWING DATA=259056 |90536|AG|PL |D|0015 |AD|49998|0065828  
DRAWING DATA=259649 |90536| C| |D|0001 | C|49998|0026043  
DRAWING DATA=265687 |90536| B| |D|0001 | B|49998|0026971  
DRAWING DATA=4052741 |90536| D| |D|0001 | D|49998|0064356  
DRAWING DATA=4052742 |90536| B| |D|0001 | B|49998|0048584  
DRAWING DATA=4911945 |90536| H| |D|0001 | H|49998|0055848  
DRAWING DATA=4911945 |90536| H| |D|0002 | G|49998|0037799  
DRAWING DATA=4912504 |90536| G| |D|0002 | G|49998|0016803  
DRAWING DATA=4912504 |94209| C| |D|0001 | C|49998|0031678  
DRAWING DATA=4912504 |94209| C| |D|0002 | C|49998|0014640  
DRAWING DATA=4912525 |90536| F| |D|0001 | F|49998|0031781  
DRAWING DATA=4912525 |90536| F| |D|0002 | F|49998|0012099  
DRAWING DATA=4912527 |90536| G| |D|0001 | G|49998|0046455  
DRAWING DATA=4912527 |90536| G| |D|0002 | G|49998|0016362  
DRAWING DATA=4912548 |90536| K| |D|0001 | K|49998|0061921  
DRAWING DATA=4912548 |90536| K| |D|0002 | K|49998|0043613  
DRAWING DATA=4912794 |90536| H| |D|0001 | H|49998|0021608  
DRAWING DATA=4912794 |90536| H| |D|0002 | H|49998|0018130  
DRAWING DATA=4912794 |90536| H| |D|0003 | H|49998|0012337  
DRAWING DATA=4912794 |90536| H| |D|0004 | H|49998|0018660  
DRAWING DATA=4912794 |90536| H| |D|0005 | H|49998|0011566  
DRAWING DATA=4912796 |90536| L| |D|0001 | L|49998|0039794  
DRAWING DATA=4912796 |90536| L| |D|0002 | L|49998|0018528  
DRAWING DATA=4912796 |90536| L| |D|0003 | L|49998|0008864  
DRAWING DATA=5223011 |53711| B| |D|0001 | B|49998|1592660  
DRAWING DATA=5223011 |53711| B| |D|0002 | A|49998|0178411

DRAWING DATA=5223383 |53711| E| |D|0001 | E|49998|0123697  
DRAWING DATA=5223460 |53711| E| |D|0001 | E|49998|0216793  
DRAWING DATA=5223493 |53711| H| |D|0001 | H|49998|0227619  
DRAWING DATA=5223493 |53711| H| |D|0002 | H|49998|0173708  
DRAWING DATA=5224209 |53711| F| |D|0001 | F|49998|0343038  
DRAWING DATA=5224209 |53711| F| |D|0002 | F|49998|0072343  
DRAWING DATA=5496689 |53711| A| |D|0001 | A|49998|0066945  
DRAWING DATA=5496689 |53711| 2|1N |D|0001 | 2|49998|0045428  
DRAWING DATA=5496917 |53711| C| |D|0001 | C|49998|0115971  
DRAWING DATA=5496920 |53711| G| |C|0001 | G|49998|0221797  
DRAWING DATA=5496920 |53711| G|PL |D|0001 | G|49998|0029071  
DRAWING DATA=5496920 |53711| G|PL |D|0002 | G|49998|0016665  
DRAWING DATA=5496920 |53711| G|PL |D|0003 | G|49998|0028927  
DRAWING DATA=5496920 |53711| G|PL |D|0004 | G|49998|0017215  
DRAWING DATA=5496920 |53711| G|PL |D|0005 | G|49998|0028286  
DRAWING DATA=5496920 |53711| G|PL |D|0006 | G|49998|0017133  
DRAWING DATA=5496920 |53711| G|PL |D|0007 | G|49998|0030549  
DRAWING DATA=5496920 |53711| G|PL |D|0008 | G|49998|0017661  
DRAWING DATA=5496920 |53711| G|PL |D|0009 | G|49998|0029155  
DRAWING DATA=5496920 |53711| G|PL |D|0010 | G|49998|0017100  
DRAWING DATA=5496920 |53711| G|PL |D|0011 | G|49998|0028833  
DRAWING DATA=5496920 |53711| G|PL |D|0012 | G|49998|0016888  
DRAWING DATA=5496920 |53711| G|PL |D|0013 | G|49998|0029055  
DRAWING DATA=5496920 |53711| G|PL |D|0014 | G|49998|0017046  
DRAWING DATA=5496920 |53711| G|PL |D|0015 | G|49998|0029006  
DRAWING DATA=5496920 |53711| G|PL |D|0016 | G|49998|0017282  
DRAWING DATA=5496920 |53711| G|PL |D|0017 | G|49998|0028962  
DRAWING DATA=5496920 |53711| G|PL |D|0018 | G|49998|0017148  
DRAWING DATA=5496920 |53711| G|PL |D|0019 | G|49998|0029292  
DRAWING DATA=5496920 |53711| G|PL |D|0020 | G|49998|0017367  
DRAWING DATA=5496920 |53711| G|PL |D|0021 | G|49998|0028754  
DRAWING DATA=5496920 |53711| G|PL |D|0022 | G|49998|0016948  
DRAWING DATA=5496920 |53711| G|PL |D|0023 | G|49998|0029201  
DRAWING DATA=5496920 |53711| G|PL |D|0024 | G|49998|0017395  
DRAWING DATA=5496920 |53711| G|PL |D|0025 | G|49998|0023866  
DRAWING DATA=5496920 |53711| G|PL |D|0026 | G|49998|0015485  
DRAWING DATA=5496920 |53711| G|PL |D|0027 | G|49998|0015855  
DRAWING DATA=5496920 |53711| G|PL |D|0028 | G|49998|0016893  
DRAWING DATA=5496920 |53711| G|PL |D|0029 | G|49998|0016175  
DRAWING DATA=5496920 |53711| G|PL |D|0030 | G|49998|0016051  
DRAWING DATA=5496920 |53711| G|PL |D|0031 | G|49998|0016447  
DRAWING DATA=5496920 |53711| G|PL |D|0032 | G|49998|0016984  
DRAWING DATA=5496920 |53711| G|PL |D|0033 | G|49998|0017011  
DRAWING DATA=5496920 |53711| G|PL |D|0034 | G|49998|0016996  
DRAWING DATA=5496920 |53711| G|PL |D|0035 | G|49998|0016753  
DRAWING DATA=5496920 |53711| G|PL |D|0036 | G|49998|0016838  
DRAWING DATA=5496920 |53711| G|PL |D|0037 | G|49998|0017041  
DRAWING DATA=5496920 |53711| G|PL |D|0038 | G|49998|0017094  
DRAWING DATA=5496920 |53711| G|PL |D|0039 | G|49998|0017729

DRAWING DATA=5496920 |53711| G|PL |D|0040 | G|49998|0017774  
DRAWING DATA=5496920 |53711| G|PL |D|0041 | G|49998|0017474  
DRAWING DATA=5496920 |53711| G|PL |D|0042 | G|49998|0017669  
DRAWING DATA=5496920 |53711| G|PL |D|0043 | G|49998|0017894  
DRAWING DATA=5496920 |53711| G|PL |D|0044 | G|49998|0017584  
DRAWING DATA=5496920 |53711| G|PL |D|0045 | G|49998|0017627  
DRAWING DATA=5496920 |53711| G|PL |D|0046 | G|49998|0017521  
DRAWING DATA=5496920 |53711| G|PL |D|0047 | G|49998|0016837  
DRAWING DATA=5496920 |53711| G|PL |D|0048 | G|49998|0016900  
DRAWING DATA=5496920 |53711| G|PL |D|0049 | G|49998|0026989  
DRAWING DATA=5496920 |53711| G|PL |D|0050 | G|49998|0016360  
DRAWING DATA=5496922 |53711| H| |E|0001 | H|49998|0260945  
DRAWING DATA=5496922 |53711| H|PL |D|0001 | H|49998|0034605  
DRAWING DATA=5496922 |53711| H|PL |D|0002 | H|49998|0022391  
DRAWING DATA=5496922 |53711| H|PL |D|0003 | H|49998|0034078  
DRAWING DATA=5496922 |53711| H|PL |D|0004 | H|49998|0021763  
DRAWING DATA=5496922 |53711| H|PL |D|0005 | H|49998|0033937  
DRAWING DATA=5496922 |53711| H|PL |D|0006 | H|49998|0019467  
DRAWING DATA=5496922 |53711| H|PL |D|0007 | H|49998|0033606  
DRAWING DATA=5496922 |53711| H|PL |D|0008 | H|49998|0021739  
DRAWING DATA=5496922 |53711| H|PL |D|0009 | H|49998|0033871  
DRAWING DATA=5496922 |53711| H|PL |D|0010 | H|49998|0021935  
DRAWING DATA=5496922 |53711| H|PL |D|0011 | H|49998|0034757  
DRAWING DATA=5496922 |53711| H|PL |D|0012 | H|49998|0021933  
DRAWING DATA=5496922 |53711| H|PL |D|0013 | H|49998|0034268  
DRAWING DATA=5496922 |53711| H|PL |D|0014 | H|49998|0021921  
DRAWING DATA=5496922 |53711| H|PL |D|0015 | H|49998|0034749  
DRAWING DATA=5496922 |53711| H|PL |D|0016 | H|49998|0022341  
DRAWING DATA=5496922 |53711| H|PL |D|0017 | H|49998|0034419  
DRAWING DATA=5496922 |53711| H|PL |D|0018 | H|49998|0020956  
DRAWING DATA=5496922 |53711| H|PL |D|0019 | H|49998|0033945  
DRAWING DATA=5496922 |53711| H|PL |D|0020 | H|49998|0022905  
DRAWING DATA=5496922 |53711| H|PL |D|0021 | H|49998|0022804  
DRAWING DATA=5496922 |53711| H|PL |D|0022 | H|49998|0023221  
DRAWING DATA=5496922 |53711| H|PL |D|0023 | H|49998|0022595  
DRAWING DATA=5496922 |53711| H|PL |D|0024 | H|49998|0023402  
DRAWING DATA=5496922 |53711| H|PL |D|0025 | H|49998|0022353  
DRAWING DATA=5496922 |53711| H|PL |D|0026 | H|49998|0023514  
DRAWING DATA=5496922 |53711| H|PL |D|0027 | H|49998|0023179  
DRAWING DATA=5496922 |53711| H|PL |D|0028 | H|49998|0022684  
DRAWING DATA=5496922 |53711| H|PL |D|0029 | H|49998|0022019  
DRAWING DATA=5496922 |53711| H|PL |D|0030 | H|49998|0024023  
DRAWING DATA=5496922 |53711| H|PL |D|0031 | H|49998|0023556  
DRAWING DATA=5496922 |53711| H|PL |D|0032 | H|49998|0023377  
DRAWING DATA=5496922 |53711| H|PL |D|0033 | H|49998|0023286  
DRAWING DATA=5496922 |53711| H|PL |D|0034 | H|49998|0023325  
DRAWING DATA=5496922 |53711| H|PL |D|0035 | H|49998|0023373  
DRAWING DATA=5496922 |53711| H|PL |D|0036 | H|49998|0022980  
DRAWING DATA=5496922 |53711| H|PL |D|0037 | H|49998|0021424

DRAWING DATA=5496922 |53711| H|PL |D|0038 | H|49998|0023582  
DRAWING DATA=5496922 |53711| H|PL |D|0039 | H|49998|0034416  
DRAWING DATA=5496922 |53711|40|1N |D|0001 |25|49998|0033665  
DRAWING DATA=5496922 |53711|40|1N |D|0002 |26|49998|0038292  
DRAWING DATA=5496922 |53711|40|1N |D|0003 |26|49998|0038235  
DRAWING DATA=5496922 |53711|40|1N |D|0004 |26|49998|0031076  
DRAWING DATA=5496922 |53711|40|1N |D|0005 |26|49998|0025396  
DRAWING DATA=5497160 |53711| B| |D|0001 | B|49998|0082959  
DRAWING DATA=5497160 |53711| 4|1N |A|0001 | 4|49998|0043853  
DRAWING DATA=5497160 |53711| 4|1N |A|0002 | 4|49998|0019199  
DRAWING DATA=5497459 |53711| B| |D|0001 | B|49998|0374398  
DRAWING DATA=5497459 |53711| A|SD |D|0001 | A|49998|0209169  
DRAWING DATA=5599412 |53711| -| |D|0001 | -|49998|0065547  
DRAWING DATA=5599412 |53711| 3|1N |D|0001 | 1|49998|0036970  
DRAWING DATA=5599412 |53711| 3|1N |D|0002 | 2|49998|0028566  
DRAWING DATA=5599896 |53711| B| |D|0001 | B|49998|0033178  
DRAWING DATA=5599896 |53711| B| |D|0002 | B|49998|0038379  
DRAWING DATA=5599896 |53711| B| |D|0003 | B|49998|0029018  
DRAWING DATA=6135802 |53711| A| |D|0001 | A|49998|0115547  
DRAWING DATA=6135802 |53711| A| |D|0002 | A|49998|0085666  
DRAWING DATA=6135802 |53711| A| |D|0003 | A|49998|0087902  
DRAWING DATA=6135802 |53711| A| |D|0004 | A|49998|0089088  
DRAWING DATA=6135802 |53711| A|PL |D|0001 | A|49998|0031156  
DRAWING DATA=6135802 |53711| A|PL |D|0002 | A|49998|0028133  
DRAWING DATA=6135802 |53711| A|PL |D|0003 | A|49998|0033100  
DRAWING DATA=6135802 |53711| A|PL |D|0004 | A|49998|0016665  
DRAWING DATA=6135802 |53711| A|PL |D|0005 | A|49998|0026302  
DRAWING DATA=6135802 |53711| A|PL |D|0006 | A|49998|0016535  
DRAWING DATA=7033299 |53711| -| |D|0001 | -|49998|0314780  
DRAWING DATA=7033299 |53711| -| |D|0002 | -|49998|0212171  
DRAWING DATA=7033299 |53711| -| |D|0003 | -|49998|0096447  
DRAWING DATA=7900174 |90536| E| |D|0001 | E|49998|0025736  
DRAWING DATA=7900174 |90536| E| |D|0002 | E|49998|0031338  
DRAWING DATA=7956567 |90536| E| |D|0001 | E|49998|0056874  
DRAWING DATA=7956567 |90536| E| |D|0002 | E|49998|0042762  
DRAWING DATA=7956567 |90536| E| |D|0003 | E|49998|0045896  
DRAWING DATA=904110 |90536| B| |D|0001 | B|49998|0038997  
DRAWING DATA=904110 |90536| B| |D|0002 | B|49998|0015653  
DRAWING DATA=908220 |90536| T| |D|0001 | T|49998|0118812  
DRAWING DATA=908220 |90536| T| |D|0002 | R|49998|0035382  
DRAWING DATA=911606 |90536| H| |D|0001 | H|49998|0039608  
DRAWING DATA=911606 |90536| H| |D|0002 | H|49998|0021263  
DOCUMENT REF DATA=MIL-STD-130 || |N |121116|A| ||  
DOCUMENT REF DATA=ISO9001 || ||160921|A| ||

### 3. REQUIREMENTS

3.1 Design, Manufacture, and Performance - Except as modified herein,  
the CABLE AND CONDUIT A furnished under this contract/purchase order shall meet the  
design, manufacture, and performance requirements specified on drawing ;6135802 (part number 6135802-59);  
cage ;53711; .



3.2 First Article Approval (Contractor Testing) - First Article Test (FAT) and approval is required.

3.3 First Article Approval (Government Testing) - First Article Test (FAT) and approval is required.

3.4 Production Lot Approval (Contractor Testing) - Production Lot Test and approval is required.

3.4.1 ;100% Acceptance Testing IAW WS20211 3.3 shall be performed on all molded cables as part of their final acceptance by the DCMC QAR as follows:

1. Visual Inspection shall be performed on all molded cables to confirm that all verifiable features of the completed cable are in accordance with the assembly drawing and all labels with the identifying Part Number and MFG CAGE Code, located on the P1 connector, are securely attached and will remain in place during the many years of handling and operational use.

2. Continuity testing completed on all molded cables IAW WS20211 3.3.2 shall be verified by the QAR to ensure compliance with WS19202 3.1 and the assembly drawing.

3. Isolation testing completed on all molded cables IAW WS20211 3.3.3 shall be verified by the QAR to ensure compliance with WS19202 3.1 and the assembly drawing. ;

3.5 Marking - This item shall be physically identified in accordance with MIL-STD-130.

3.6 Soldering - The requirements for soldered electrical and electronic assemblies shall conform to IPC J-STD-001, Class ;3; .

3.7 Manufacturing and Design - The CABLE AND CONDUIT A furnished under this contract/purchase order shall meet the material and physical requirements as specified ;J-STG-001G and or latest REV; .

#### 4. QUALITY ASSURANCE

4.1 Responsibility for Inspection - Unless otherwise specified in the contract/purchase order, the Contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract/purchase order,

the Contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.2 First Article Test/Inspection (Contractor) - The Contractor shall conduct ;Non-destructive; First Article Test/Inspection on ;one; unit(s) in accordance with requirements ;for acceptance of material called out in drawings; .

4.3 First Article Compatibility Test (Government) - Upon satisfactory completion of the First Article Test/Inspection by the Contractor, ;one; unit(s) shall be shipped to ;NSWC-PHD, MK41 VLS group; for compatibility test to assure satisfactory, form, fit and function within the applicable end item or system.

Government First Article Compatibility Test shall consist of ;destructive; testing. If the testing is nondestructive, the first article sample ;will; be returned.//

4.4 ;100% Inspection IAW WS20211 Section 3.3 is required. QAR shall conduct visual inspection per WS20211 3.3.1 and validate the results of the continuity and isolation testing (WS20211 3.3.2 and 3.3.3) as part of the acceptance process for each finished cable.;

4.5 Records of Inspection - (This requirement is not applicable to Government Purchase Orders) Records of all inspection work performed by the Contractor, as referenced elsewhere in this contract, shall be kept complete and available to the Government during the performance of the contract and for a period of four years after final delivery of supplies.

4.6 Responsibility for Compliance - All items must meet all requirements of this contract/purchase order. The inspection set forth in this specification shall become a part of the Contractor's overall inspection system or quality program. The absence of any inspection requirements shall not relieve the Contractor of the responsibility of assuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract/purchase order. Sampling in quality conformance

does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to acceptance of defective material.

4.7 Records - Records of all inspection work by the Contractor shall be kept complete and available to the Government during the performance of contract/purchase order and for a period of 365 calendar days after final delivery of supplies.

4.8 ;First Article Test/inspection report- the contractor shall prepare and submit a report in accordance with the Contract data Requirements List (DD Form 1423) The report shall be approved prior to production.;

## 5. PACKAGING

5.1 Preservation, Packaging, Packing and Marking - Preservation, Packaging, Packing and Marking shall be in accordance with the Contract/Purchase Order Schedule and as specified below.

MIL-STD 2073 PACKAGING APPLIES AS FOUND ELSEWHERE IN THE SCHEDULE

## 6. NOTES

6.1 Ordering Information for Document References - The Department of Defense Single Stock Point (DODSSP), Website <http://www.dsp.dla.mil/>, provides product information for the Department Of Defense Index Of Specifications and Standards (DODISS)

(i.e. Military/Federal Specifications and Standards), Data Item Descriptions (DIDs), and other DODSSP Products. Most Specifications can be obtained directly from <http://quicksearch.dla.mil/>

A. Availability of Cancelled Documents - The DODSSP offers cancelled documents that are required by private industry in fulfillment of contractual obligations in paper format. Documents can be requested by phoning the Subscription Services Desk.

B. Commercial Specifications, Standards, and Descriptions - These specifications, standards and descriptions are not available from Government sources. They may be obtained from the publishers of the applicable societies.

C. Ordnance Standards (OS), Weapons Specifications (WS), and NAVORD OSTD 600 Pages - These type publications may be obtained by submitting a request to:

Commander, Indian Head Division, Naval Surface Warfare Center  
Code 8410P, 101 Strauss Avenue  
Indian Head, MD 20640-5035

D. On post-award actions, requests for "Official Use Only" and "NOFORN" (Not Releasable To Foreign Nationals) documents must identify the Government Contract Number, and must be submitted via the cognizant Defense Contract Management Command (DCMC) for certification of need for the document. On pre-award actions such requests must be submitted to the PCO for certification of need for the document.

E. NOFORN Military Specifications and Standards (including Amendments, Change Notices and Supplements, but NOT interim Changes) to be ordered from:

Contracting Officer  
NAVSUP-WSS  
Code 87321

5450 Carlisle Pike  
P.O. Box 2020  
Mechanicsburg, Pa. 17055-0788

F. Nuclear Reactor Publications Assigned NAVSEA Documents and Identification Numbers (i.e. NAVSEA Welding Standard, NAVSEA 250-1500-1) are to be ordered enue:

Commanding Officer  
NAVSUP-WSS  
Code 009

5450 Carlisle Pike  
P.O. Box 2020  
Mechanicsburg, Pa. 17055-0788

G. Technical Manuals Assigned NAVSEA Identification Numbers (i.e. NAVSEA Welding And Brazing

Procedure, NAVSEA S9074-AQ-GIB-010/248) are to be ordered from:

Commanding Officer

NAVSUP-WSS

Code 1 Support Branch

700 Robbins Avenue

Philadelphia, Pa. 19111-5094

H. Interim Changes and Classified Specifications must be obtained by submitting a request on DD Form 1425 to NAVSUP-WSS.

6.2 Notice To Distributors/Offerors - Consideration for award of contract shall be given only to authorized distributors of the original manufacturer's item represented in this solicitation. If you desire to be considered as a potential source for award of

this contract, proof of being an authorized distributor shall be provided on company letterhead signed by a responsible company official and sent with your offer to the Procurement Contracting Officer.

6.3 In accordance with OPNAVINST 5510.1 all documents and drawings provided by the U.S. Navy to perspective Contractors must include a "Distribution Statement" to inform the contractor of the limits of distribution, and the safeguarding of the information contained on those documents and drawings.

There are 7 (seven) separate distribution statement codes used for non-classified documents and drawings. The definition for each is as follows:

A... approved for public release; distribution is unlimited.

B... distribution authorized to US Governments agencies only.

C... distribution authorized to US Government agencies and their contractors.

D... distribution authorized to DoD and DoD contractors only.

E... distribution authorized to DoD Components only.

F... further distribution only as directed by Commander, Naval Sea Systems Command, code 09T.

X... distribution is authorized to US Government agencies and private individuals or enterprises eligible to obtain export controlled technical data in accordance with OPNAVINST 5510.161.

Manufacturing sources interested in becoming qualified for support of future requirements for this item should submit their interest in writing to the Contract Officer, to include a summary of the company's applicable capabilities. This will be forwarded to the appropriate point of contact at NSWC, PHD for evaluation.

DATE OF FIRST SUBMISSION=ASREQ

Block 12 - Submit for approval prior to production.

Block 14A - The deliverable item specified as information copy shall be boldly marked as "Information Only".

Block 14 - Port Hueneme Division, Naval Surface Warfare Center, ;MK 41 VLS Engineering Activity ; ,Port Hueneme, CA 93043-5007.

DATE OF FIRST SUBMISSION=045 DAC

Block 12 - Submit for approval prior to production.

Block 14A - The deliverable item specified as information copy shall be boldly marked as "Information Only".

Block 14 - Port Hueneme Division, Naval Surface Warfare Center, ;MK 41 VLS Engineering Activity ; ,Port Hueneme, CA 93043-5007.

DATE OF FIRST SUBMISSION=ASREQ

100% Inspection IAW WS20211 3.3 is required. Test reports for sections 3.3.2 and 3.3.3 shall be provided to the QAR as part of the acceptance process.

DATE OF FIRST SUBMISSION=ASREQ  
;GOVERNMENT COMPATIBILITY TESTING TO BE COMPLETED 45 DAYS FROM RECEIPT OF FAT  
UNIT / TEST REPORT FROM CONTRACTOR.;

DATE OF FIRST SUBMISSION=ASREQ  
Request for Waiver- Prior submission  
Based on past successful delivery of material on contracts


Country:  
United States

Published date:  
Mar 16 2022

Deadline:  
Apr 11 2022

Contact:  
Telephone: 2157373766

Email:  
DANIEL.MACDONALD@DLA.MIL

Link:  
[Link to original](#)  


**Please register**

Registering is free and only takes a moment.

[Register](#) [Login](#)

Open Contracts ID:  
ocds-0c46vo-0421-0da8434e1115440a82b21dc7dae6b400

Saved on:  
Mar 17 2022

Source ID:  
0da8434e1115440a82b21dc7dae6b400

OCDS JSON:

<https://openopps.com/tenders/cable-and-conduit-a/ocds-0c46vo-0421-0da8434e1115440a82b21dc7dae6b400?format=json>

---