GOVERNMENT OF PAKISTAN PAKISTAN PUBLIC WORKS DEPARTMENT

6. EE CCD-III/AB//40

Dated: 13/04/2021.

TENDER NOTICE

Tenders are hereby invited in sealed covers from approved Government contractors who have the relevant field of specialization and dully registered/ renewed their enlistment for 2021-22 with Pakistan Engineering Council, in relevant category (C-6 and above). The bidding documents can be purchased up to 09-05-2022, which should reach in the office of the undersigned up to 10-05-2022 at 12.00 Noon and will be opened on the same day at 12.30 P.M.

S. No	Name of works	Estimated cost	Earnest money	Cost of Tender
1.	Annual repair of Office and Residential Building at NAB (B) Complex Quetta.	676478.00	04% of Bid	2000.00
2.	Special repair of Office and Residential Building at NAB (B) Complex Quetta.		04% of Bid	2000.00

Note: In case the tenders are not sold / opened on the date mentioned above due to some circumstances then the date may be considered as 16-05-2022 and 17-05-2022, respectively, with same terms and conditions.

TERMS & CONDITIONS:-

- 1. Application for purchase of tenders on printed letter head of firm/contractor.
- Attested copies of partnership deed, power of attorney / affidavit in favour of any individual 2. authorized to receive / submit tender documents.
- 3. The tender shall be issued only to the authorized representative of the firm having legal authority letter/power of attorney in case of firm the applicant shall have to produce partnership deed duly registered with the court of law.
- No tenders will be sold by post or on the date of opening of tender. 4.
- Earnest money as specified above @04% of the Bid amount in the shape of call deposit as provided in PPRA Rule-25, with any local Government approved bank pledged in favour of the Executive Engineer Central Civil Division No-III Pak PWD Quetta..
- 6. NTN should be produced at the time of purchase of tender.
- Experience Certificate in relevant field and at least three work orders of the Projects 7. completed by the firm during the last 05 years
- The competent authority reserves the right to accept or reject any or all tenders by quoting 8. reasons as per provision of PPRA rules-33 (1), (2) and (3) of 2004.
- Authority letters for any representative of firm by Chief Executive of the firm / company. 9.
- Each page of the bid must be signed with stamp of company. 10.
- Those Contractors who have quoted abnormally below rates as compared with Engineers 11. estimate they will furnish an additional CDR equal to the difference of cost along with rate analysis to protect employers interest.
- List of machinery equipment and technical staff working with firm along with documents. 12.
- The affidavit on stamp paper of Rs:100/- certifying that the firm has not been ever black 13. listed by the Government / Autonomous body.
- An affidavit regarding authenticity of all information provided for purchase of tenders should be enclosed with the documents if any information is found incorrect fake or forged the tender of the firm will be cancelled and legal action will be taken against the firm.
- Financial soundness certificate of the Firm from authorized Bank must be attached with the 15. application.
- All the documents required as mentioned above should provided at the time of purchase of 16.
- Tender Notice can also be seen on PPRA web site i.e. www.ppra.org.pk 17.
- 18. Notice Board.

Executive Engineer Central Civil Division No. III Pak P.W.D. Quetta.

GOVERNMENT OF PAKISTAN PAKISTAN PUBLIC WORKS DEPARTMENT

NO.EE.CCD.III/AB//40

Dated. 13 /04/2022.

To,

The Director, Press Information Department, Government of Pakistan Quetta. Ph:0819203424

Subject: -

ADVERTISEMENT OF TENDER NOTICE.

Enclosed please find herewith Notice inviting tender for publication in daily leading News papers (one Urdu and one English).

The bill in triplicate along with copies of newspapers and PPRA's copy of uploading in which insertion is made, may be submitted to this office for payment.

Encl: - as above.

Executive Engineer, Central Civil Division No. III, Pakistan P.W.D., Quetta, Ph: No: 081-9211102.

Copy to: -

The Chief Engineer (W) Pak PWD Quetta.
 The Superintending Engineer (QS), Director General's Office, Pak PWD Islamabad.
 The Superintending Engineer, Central Civil Circle, Pak PWD Quetta.
 PPRA, G-5/2 Islamabad/Website (by fax)
 The Divisional Accounts Officer of this office.
 Notice Board

EXECUTIVE ENGINEER.

Executive Engineer
Central Civil Division No. III
Pak P.W.D. Quetta.

BASED ON PAK PWD SCHEDULE 2012
DETAIL MEASUREMENT

1	Description CIVII MODIA	_	NO	L		T	w		H/D			
NO	CIVIL WORK						_	-	חוס	Quantity	Unit	H.
	providing and applying two to three coats of	` ,							h (1)			
	oversell chemical (Brooks or equivalent) (B type)							Danie V			S-ET-C	
1	(Σ ι)ρε)	4		1		-	1	-				
1	8 type houses	3		1		50	_	40	_	8000		
10	type	3	-	1		48	,'	35		4725	-	
\neg		-	/_	1		42		37		3108		/
F	Providing and laying first class solid burnt brick				,			,	Total	15833	Sft	
2 n	nasonry set in cement mortar 1:4	1		X		20	/		/	/		
_				-		30	_	0.75	5	225		
, F	Providing and fixing M.S. moulded steel door		-	-			-	_	Total	225	/	
3 f	rames door	13	1.	1		17.5					-	NAME OF
-			/		,	17.5	-	,		52.5		
4	P/F flushed door shutter	1		3	_	-	/		Total	52.5	-	
			+	3	_	3		6.5		97.5		/
5 F	P/F wire gauze shutter	4	X	4	_	_			Potal	97.5	Sft	/
			-	4	_	3		6.	5	78	1	/
6	Providing and fixing skirting tile		+		/				Total	78	Sfi	
	Bath Room	-	X	1				/	, and William	-		
		1	1	5		17.5	/		4.3	378.879	1	
	Deduct Door	-	-	_	/	NE		/	Total	378.87	5	
-	2 C G G C C G G G G G G G G G G G G G G	/	1	5		2.5	5		4.3	3 54.12	5/	
7	Providing and laying floor of tiles	_	1		/			/	Net Total		_	
-	r roviding and laying floor of tiles		1	-5	/ Lu		6			6 18	_	
		-64							Total		0 Sf	1
	PLUMBIN	GV	NC	RK	1			,			1	
1	P/F super tuff tank 400 Glln	Τ.	7				1	_			1	
		+ 4	4	1		•	9		A Section		9	
	Providing PPRC pipes (Liansu make) and	1	X		_		+	/	Total	~	9 N	09
2	specials, etc; (1" thick 25mm)	4	1	19		2	15					
141			+		/		-		7-4-1	3:		
3	P/F foot valve 1" dia	1	1	- 4	-	_	+		Total	3:	15 R	ft /
		-	4				-				7	
	Providing and fixing 1 inches (15 mm) dia full wa		-		/		-		Total		7	los
4	gun metal valves	y	1	6							1	
		-	+		-		+		Total	-	6	Vos
	Providing and fixing standing wall shower of C	P	+			-	+	-	Total	-	6 1	vos
:	brass 3 knobs of approved quality mixer unit.		1	- 2							1	
				/	1/				Total	-	3	Nos
	6 P/F basin mixer	61 H	1		1				10101		7	10,
									Total			Nos
	7 C.P. Mixer Tap 1/2 inch dia for sink.	_	1	1	7	-			Total		7	NOS
		+	-	_	1		-		Tabal		-	. /
-	8 Providing and fixing W.C Pan,		4		1		-		Total			Nos
desi	gir fortiding and fixing 14.0 f all,		u		-	-	-				X	/
-	DIE Europea atila vibita alared andhaniv	-			1	4		Acres 10	Total		X	Nos
	P/F European style white glazed earthenwa 9 W., C pan complete	116	/1	/	1						1	
	yv.,o pan complete	-	-		-				Total		_	/
	0 C.P. Bib cock 1/2 inch dia.	-	4	1	6				Total			Nos V
	UIC.P. DID COCK 1/2 IIICH dia.		1	3	00				A SHEET	and the same of	36	1
1				In the second	100		100		Total			Nos

Asstr: Lacentive Loginver III Central Continuision No: III Pak FWD, Quetta.

1 3		providing and fixing water tank made of food grade polyethylene material 400 gallon (Supper tuff) i/c cost of specials and cartage upto site as per direction of Engineer in charge.				
2 M	İ	Providing PPRC pipes (Liansu make) and specials, etc; inculding fixing, cutting and fittings, complete with and ncluding the cost of and cartage within 10 miles, (16.09 km) 3/4 inch (20 mm) dia pipe.	9	Each	16915.8	152242.2
3 3:		Providing and fixing cast iron foot valve with flanged ends complete with a strainer suitable for fixing to 1 inch (25 mm) dia. suction pipe including 1/8 inches (3.2 mm) thick rubber washer	/315	RET	420	37800
4 3	07/8	Providing and fixing 1 inches (25 mm) dia full way gun metal valves with wheels threaded or flanged ends with rubber washers, (standard pattern)	7	Nos	770	5390
5 (5	301/20	Providing and fixing standing wall shower of CP brass 3 knobs of approved quality mixer unit and moveable shower head complete	6	Nos	884.75	5308.5
	BR/4205	C.P. Mixer Tap 1/2 inch dia for wash basin	/ 2	Nos	4489.28	8978.56
6	5174203	Dasiii				_

/		Providing and fixing 1-1/2 inches (38	17-7-19	1 Total		
1		mm) thick solid core deodar wood				
18	1	dushed veneered door shutters, with and including the cost of commercial				
		blywood facing 3 mm. thick (3 ply) on				
		both faces, fixed over best quality	Annual L			Y A
	-	deodar wood frame 2 inches wide	The state of	and the	1 1 2 2 3 1	n in little
		alround 6 inches wide lock rail and 2nd				1-7
		class deodar wood solid core, i/c., 1/4			중 그는 지난	
		inch thick best quality deodar wood	Mark D			
		lipping on all sides as per approved			1	
		drawing, manufactured under power				
		driven hydraulic press, including the				
		cost of approved iron fittings but				214
		excluding the cost of handles and				-
4 1	20/61-A	locking arrangement.			1	1
-			~			
+	100	Providing and fixing 1-1/2 inches (38	87.5	SPT	5/1.676	55/138.41
		mm) thick best quality deodar wood				
- 1		wire gauze shutters fully wire gauzed			730	
		with galvanized iron wire gauze of 24				W. T.
, p		gauge and 12 mesh to an inch (25 mm)				
		with approved iron butt hinges, spring				
_	120/126	hinges, tower bolts etc., as required.			/	
	120/120		_/			
		Providing and fixing 1/4 inch or 6.4 mm	78	SFT (506.98	39544.44
		(approx.) thick approved Pakistani				
	Miles !	make coloured glazed tiles 6" X 6" (152				
		mm X 152 mm) size in dado and				in the said on the
	1	skirting in ground floor, over 1/2 inch		24		
	De com	(13 mm) thick base of cement mortar				
		1:3 setting of tiles in slurry of grey				
		cement over mortar base, including filling joints and washing the tiles with				
		cement slurry of matching colour,		the bart		
		curing and cleaning etc. complete.				
	6 118/44					
			/324.7	5 %SFT	13113.87	42587.29283
		Providing and laying floor of 6mm			Hall X	
		(approx: 1/4") thick coloured glazed				
		tiles 12" x 12" (304mm x 304mm) of master make (Pakistani) first grade in				
		ground floor laid over 1" (25mm) thick				
	HI Z	cement mortar 1:2 (1 cement and 2				
		sand) including jointing and washing				
		the tiles with white cement slurry a				
		matching colour (by using pigment in		/	/	
	7 117/6	white cement) and curing etc. complete.		/ /		
	/ 11//0.	Complete.	10	30 %SFT	18359.6	33047.28
			18	30 703FT		1104607.8
					Total	1104607.8
		etaintik Teatrico sumi hare se avec di esse Gamentia Serimene e e e				
					Total SI Total NSI	1104607.795 870815

NAME OF WORK: Special Repair of Residential Building at NAB(B) Complex Quetta
BASED ON PAK PWD SCHEDULE 2012

Abstract of Cost

	SH/Item No	Description	Quantity	Unit	Rate	Amou	ınt
·	110	CIVIL WORK		1	1	7	
		and the second s			1		
		Providing and applying two to three coats of oversell chemical (Brooks or equivalent) with cleaning the roof properly i/c one coat of primer plastic PVA chmeical, filling the joints with flexible chemical and two coat of TNT 2000 with cement mixture and labor					
		charges etc complete as per direction of Engineer-in-Charge.					,
1	MR			/			
		Providing and laying first class solid	1583	SISFT	4	55	870815
2	112/26+7 9	burnt brick masonry set in cement mortar 1:4 in straight or curved walls 4-1/2 inches (114 mm) and less in thickness including scaffolding, raking out joints and curing etc. complete in ground floor superstructure.					,
			62	5 %CFT	2362	20.01 531	45.022
		Providing and fixing M.S. moulded steel door frames of 5.73" x 2-1/2" (146 mm x 63 mm) manufactured from mile steel sheet of 18 gauge (1.41 mm conforming to B.S.S. 1245 having a double rebate size 1-1/2" x 1/2" (3 mm x 12 mm) provision of 3 Nos. M.S. plate, section 1-1/2" x 1/4" (38 mm x mm) (2 Nos. 6 inch long welded with frame at not less than 10 points and Nos. 12 inch long welded with frame a not less than 20 points), with holes an threads for fixing steel hings, fitted with one locking box of same sheet (poinwelded inside the frame), 6 Nos. inches long flat iron fixing lugs of 1-1/4 x 3/16" section, treated with special reoxide primer coat all around includir cutting holes and filling the cavity with cement concrete 1:2:4 etc. in any float any height complete as directed the Engineer-in-Charge	Side of the control o				
	The same			/			•
	3 119/44						

-	the forwards having		_		Total	20	0.00	No
7	C.P. Mixer Tap 1/2 inch dia for wash basin			/				
			4	25		2	5.00	
	Brass Stop cock :dia 3/4 inch (20mm).	_	_		Total	Charles to the control of the contro	_	No
4	Brass Stop cock (dia 3/4 men (20mm).				1			
			1	48		4	5.00	
	Glazed Earthen Ware low level flushing cistern				Total		-	No
5	3 gallon (13.6 Litre) capacity Pakistani.							
	17.51 4607			/				
			1	30			10.0	
						The second secon	30.08	
6	Providing and wrapping tightly round pipes upto 6 inches (150 mm) dia Hessian soaked in bitumen paint of approved quality				Tota		30.0	DNO
		1	100	/		1973		
		1	100				10	0
		1	10.	.0000			1	.0
-	Providing and fixing 3 inches (80 mm) dia full				Tota	16	11	0 RFT
7	way gun metal valves with wheels threaded or flanged ends with rubber washers, (standard pattern)						10	
		2	1	1				4
				R 1784	Tot	21		7 No

Assti: Executive Engineer III Centrat Civil Division No. III Pak PWD, Quetta.

NAME OF WORK: Special Repair of office Building at NAB(B) Complex Quetta BASED ON PAK PWD SCHEDULE 2012 DETAIL MEASUREMENT

S.No	Description							
	Providing and laying water proofing of 1-1/2" to		No	L	W	H/D	Quantity	Unit
	2 inches (38 to 51 mm) thick 1:2:4 cement concrete using graded screened bajri 3/8 to 3/16							
	IIIIOII (4 to 2 IIIIII) IIIICK In string 1 1/41			Nac Mil				10-11
5					Contract of the Contract of th			
				-		-		
					ALL IPP			110
	an solida oli dibuliti finor but aval.	1.8						
	ocst of M/S angle.							
			/		,			
		6	1	40.0			1440	
	TAGE OF THE PERSON NAMED O				Tot	al	1440	-
77	Providing and applying two to three coats of			1177			1440	351
	oversell chemical (Brooks or equivalent) with							
	cleaning the roof properly i/c one coat of							- 177
	primer plastic PVA chmeical, filling the joints			The same				
1	with flexible chemical and two coat of TNT 2000							
	with cement mixture and late		100			-		18
	with cement mixture and labor charges etc							
	complete as per direction of Engineer-in- Charge.					- 41		
	charge.		/					
10	Providing and fixing skirting tile	6	7	404	62		1440	Sft
LATE	Corridor	-/				/	garage -	-
		2	3	20	0.5		60	
11	Providing and laying floor of tiles(Corridor)	1				Total	60	
NAME OF THE OWNER, OWNE	Room	2	/3	_ 20	8		960	1
	Bath Room	4	1	12	20		960	
		10	1	6	/ 5		300	
						Total	2220	Sft
							A THE RESERVE AND	
	PLUMBING WORK			81111				
	Providing and fixing Pakistani best quality	Tilly 15						
	European style white glazed earthenware W Cl							
	pan complete with and including the cost of plastic seat and buffers, 13.6 litres best quality							
	low level plastic flushing cistern with internal							
1	fittings complete, P.V.C flushing pipe with fittings							
	and making requisite number of holes in walls.							
	plinth and floor for pipe connections and making							
	good in cement concrete 1:2:4		//				Live .	
10.00		/	/				/	
DAZTI VEGU		1	20				20.00	
NOTE !	CP Muslim Bibcock with out muslim shower.				Tot	tal	20.00	No
2	Sisson mai out musiim shower.			/	/	The state		
BAR			1	20			20.00	
16339	18.72 de 10 april 18.00 de 1					the second second	20.0	

NAME OF WORK: Special Repair of office Building at NAB(B) Complex Quetta

BASED ON PAK PWD SCHEDULE 2012

		ABSTRACT OF (LOST			
.No	SH/Item No	Description	Qty	Unit	Rate	Amount
	Civil Wo			all and	A DECEMBER	· ····ount
1 1	.08/25-A	Providing and laying water proofing of 1-1/2" to 2 inches (38 to 51 mm) thick 1:2:4 cement concrete using graded screened bajri 3/8 to 3/16 inch (4 to 2 mm) thick in strips 1-1/4' wide laid on next day in full length of the roof with using M/S angle 1-1/2" x 1-1/2" x 3/16" including compecting, curing and removal of angles iron as directed on ground floor but excluding the ocst of M/S angle.				
+			1440	%SFT	2220.50	
2 1	118/44	Providing and fixing 1/4 inch or 6.4 mm (approx.) thick approved Pakistani make coloured glazed tiles 6" X 6" (152 mm X 152 mm) size in dado and skirting in ground floor, over 1/2 inch (13 mm) thick base of cement mortar 1:3 setting of tiles in slurry of grey cement over mortar base, including filling joints and washing the tiles with cement slurry of matching colour, curing and cleaning etc. complete.	1440	/ojr I	2329.62	33547
+		A STATE OF THE STA	60	%sft	13113.87	7868.322
3	117/63	Providing and laying floor of 6mm (approx: 1/4") thick coloured glazed tiles 12" x 12" (304mm x 304mm) of master make (Pakistani) first grade in ground floor laid over 1" (25mm) thick cement mortar 1:2 (1 cement and 2 sand) including jointing and washing the tiles with white cement slurry a matching colour (by using pigment in white cement) and curing etc. complete.	/			700.32
-35		Providing and Alice Address of the Control of the C	2220	%sft	18359.6	407583.17
4	MR	Providing and applying two to three coats of oversell chemical (Brooks or equivalent) with cleaning the roof properly i/c one coat of primer plastic PVA chmeical, filling the joints with flexible chemical and two coat of TNT 2000 with cement mixture and labor charges etc complete as per direction of Engineer-in-Charge.				

1440 sft

NAME OF WORK: Annual Repair of office Building at NAB(B) Complex Quetta BASED ON PAK PWD SCHEDULE 2012

	DETAIL MEASU	JREN	IENT					
S.No			No	L	W	H/D	Quantity	Unit
1	Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) of approved make and shade to walls and ceiling etc., including scraping cleaning the old surface in any floor.					.,,5	quantity	Onit
	Room	A	22	1/2		172	1267	+
		14	22	12		1		
2	Repainting two coats with enamel paint of approved make and shade to wood work including scraping and sand papering the surface as directed by Engineer-in-Charge in any floor.				Тс	otal	2534	4 SFT
	Room	50	2.250	3.6	1		7 236	2 54
		- 7	,		Т	otal		2.5 SF
3	Emulsion paint two renewal coats	1	3	1	-			96
		2	4	1			,	44
		1		1	/	_	/	108
		1		8 1	3		-	715
		/	1	4 10.1	8	11-11-11-11-11-11-11-11-11-11-11-11-11-	14 447	.92
			,			Tot	al 4110	.92
4	Plastering 3/4" (19 mm) thick in patches in cement sand mortar 1:4 including curing and scraping old damaged portion in regular shape and removal of rubbish from the site etc. complete as per direction of Engineer-in-Charge in ground floor.							
T-Sala		3	0	1 8	.0		9	160
	The first of the control of the cont		/	/	/		7	,

Assit: Executive Engineer III Central Concentration No: III Pak PWD, Quetta.

Total

3600

5760 SFT

PAKISTAN -

PAKISTAN PUBLIC WORKS DEPARTMENT

NAME OF WORK: Annual Repair of Residential Building at NAB(B) Complex Quetta
BASED ON PAK PWD SCHEDULE 2012

DETAIL MEASUREMENT

Description	ne production has	NO		L		W		H/D	Qu	antity	Unit
CIVIL WOR	K						i u				
				,	1	the st	1			/	
Distemper (Paintex ICI Dulux)	4	/	1								/
distemper (r dimension	5	1	8	/		11141	_				/
	3		5		13	-			_		CH
		41						Total		7938	Sit
Repainting two coats with enamel paint of approved make and shade to wood work including scraping and sand papering the surface as directed by Engineer-in-Charge in any floor.				/					/		
Room	100	2.2	250		3.0	~			7		
		/	- H D	_		1	To	tal	1		
Emulsion paint two renewal coats	3	11	3			/			_		-
	4		4	_	_	/			_		_
	B	112	4	/		/					_
	1			_		_	4		/		_
	/1	M	4		10.18	/			11		
	THE R							Total		6750.9	2
	100	/	_	-		/			-		/
	_	1	12	_		/			-		
		/	Z			-		Te su Ten	-		-
A Type	6		2		14				V		/
	F	-		-		/		1			
/2" Plastering on walls internal side 1:4	-	4		/		1	_	-			_
The state of the s	7	1_		/		_			-		-
	1	1	5				10	4			-
		1	_	/		1			108		_
3/4" Plastering on walls external side 1:4	_	4	, 1	/				_			-
		/	1	/		/			-		_
	_	-	$\frac{1}{2}$	/		/		-	771 B		_
	-	/	3	1		9/	10	Total			8 sft /
	Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) Repainting two coats with enamel paint of approved make and shade to wood work including scraping and sand papering the surface as directed by Engineer-in-Charge in any floor.	CIVIL WORK Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) State Repainting two coats with enamel paint of approved make and shade to wood work including scraping and sand papering the surface as directed by Engineer-in-Charge in any floor. Room 100 Emulsion paint two renewal coats 3 Approximately appear to the surface as directed by Engineer-in-Charge in any floor. Repainting Iron Work with enamel paint Type 3 Type 4 Type 6 Type 6 Type 7 Plastering on walls internal side 1:4	CIVIL WORK Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) S Repainting two coats with enamel paint of approved make and shade to wood work including scraping and sand papering the surface as directed by Engineer-in-Charge in any floor. Room 100 2 Emulsion paint two renewal coats 3 A A A B Repainting Iron Work with enamel paint C Type 3 Type A Type 6 A Type 72" Plastering on walls internal side 1:4	CIVIL WORK Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) S Repainting two coats with enamel paint of approved make and shade to wood work including scraping and sand papering the surface as directed by Engineer-in-Charge in any floor. Room 100 2.250 Emulsion paint two renewal coats 3 3 4 4 7 5 7 Repainting Iron Work with enamel paint C Type 3 Type 4 2 7 7 Plastering on walls internal side 1:4 3 1 7 5 7 7 Plastering on walls external side 1:4 2 1 7 7 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CIVIL WORK Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) 5 8 8 8 8 9 8 8 8 9 8 8 8 8	CIVIL WORK Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) Solve and shade to wood work including scraping and sand papering the surface as directed by Engineer-in-Charge in any floor. Room 100 2.250 3.0 Emulsion paint two renewal coats 3 3 12 3 4 16 1 1 10.18 Repainting Iron Work with enamel paint C Type 3 Type 3 Type 4 3 10 10 12 2 12 10 15 10 17 10 18 10 18 10 19	CIVIL WORK Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) 5	CIVIL WORK Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) S S S X2 15 3 5 13 14 Repainting two coats with enamel paint of approved make and shade to wood work including scraping and sand papering the surface as directed by Engineer-in-Charge in any floor. Room 100 2.250 3.0 Emulsion paint two renewal coats 3 3 12 Emulsion paint two renewal coats 3 4 16 Sepainting Iron Work with enamel paint 5 13 A 16 A 16 A 10.18 Repainting Iron Work with enamel paint 6 12 A 10.18 Repainting Iron Work with enamel paint 7 14 A 10.18 A 10.	CIVIL WORK Distempering three renewal coats with vinyle distemper (Paintex ICI Dulux) 5	Description	Description

Asstt: Executive Engineer III Central Civil Division No: III Pak PWD, Quetta.