

| | | | | | | | |
|--|--|--|--|--|--|--|--|
| | | | | | | | |
|--|--|--|--|--|--|--|--|

All existing galvanised metal sheet and false ceiling of Toilet and Store damaged

SLOPE

Damaged RWP

Remove existing galvanised metal sheets and false ceiling of Exhibition Room no.2 damaged

Damaged shingles

Damaged RWP

Remove existing galvanised metal sheets and false ceiling of Exhibition Room no.2 damaged

| | |
|---------|--|
| mp. No. | |
| S | |

revision